

## QS COMPARISON/ TRACKLOK®



## Q.S OF BRACING OVER 2.4m SPAN - TRACKLOK®

| Description | Qty    | Rate              | Total    |
|-------------|--------|-------------------|----------|
| TRACKLOK®   | 2      | \$30.00 per brace | \$60.00  |
| Labour      | 1hr    | \$60.00 per hour  | \$60.00  |
| Steel Stud  | 2x2.4m | \$4.80 per length | \$9.60   |
| Fixings     | 1 Sum  | \$10.00           | \$10.00  |
|             |        |                   | \$139.60 |
|             |        | \$69.80 per brace |          |

## Q.S OF BRACING OVER 2.4m SPAN - Cut & Bent Stud

| Description       | Qty     | Rate              | Total        |  |
|-------------------|---------|-------------------|--------------|--|
| Steel Stud        | 2 x2.4m | \$4.80 per length | \$9.60       |  |
| Timber 90.45 H1.2 | 2.4m    | \$6.50 per length | \$15.60      |  |
| Labour            | 1.5hrs  | \$60.00 per hour  | \$90.00      |  |
| Fixings           | 1 Sum   | \$10.00           | \$10.00      |  |
|                   |         |                   | \$125.20     |  |
|                   |         | \$62.60 p         | 60 per brace |  |

Notes: Does not allow for seismic seperation. Voids ceiling installers PS3. Voids ceiling manufacturers warranty. Fails to meet AS/NZS1170.5

## Q.S OF BRACING OVER 2.4m SPAN -Timber, Sleeve & Bent Stud

| Description              | Qty        | Rate               | Total    |
|--------------------------|------------|--------------------|----------|
| Timber Ex100x50mm 1x2.4m |            | \$3.80 per lm      | \$9.12   |
| Steel Stud               | 2x2.4m     | \$4.80 per length  | \$9.60   |
| Bolts                    | 6          | \$2.00 per bolt    | 412.00   |
| Sleeve to Fit Bol        | t 2        | \$5.00             | \$10.00  |
| Labour                   | 2hr 52mins | \$60.00 per hour   | \$151.20 |
|                          |            |                    | \$191.92 |
|                          |            | \$ 95.96 per brace |          |

Notes: Does not allow for seismic seperaGon. Voids ceiling installers PS3. Voids ceiling manufacturers warranty. Fails to meet AS/NZS1170.5

06.2019 www.tracklok.com

 $<sup>^{\</sup>star}$  Figures sourced from practising Quantity Surveyors and excludes builders margins in all cases.